Sheet1

N.B. All items are 1973/74 T150V and used unless stated otherwise.

Air cleaner ass.	1	New
Battery carrier	5	4 11005 (1 1/1 1/1 1/1
Bracket, fuel tank mounting	2	1 x export, 1 x H&GE (chromed/rusty)
Bracket, h/light – L	7	T
Bracket, h/light – R	8	Two chromed (1 x NOS)
Bracket, no. plate, bottom	3	
Bracket, no. plate, top	3	=
Bracket, number plate	1 pr	For 1971/72
Bracket, oil tank, bottom	3	
Brackets, front mudguard, wire stay type	4 prs	For 1971/72 conical hub
Brake caliper	5	
Brake rod	3	
Brake rod, adjuster nut	1	
Brake rod, lever, front	1	
Brake, disc	3	1 x 254mm, 2 x 248mm
Brake, rear, T160, caliper carrier/torque arm	1	
Brake, rear, torque stay	4	
Cable protection strip, rear light	4	
Electrics mounting plate	2	
Engine plate, front	5	
Engine plate, rear – R	1	
Footrest – L	3	
Footrest – R	2	
Footrest , slider – R	1	
Footrest, pillion	1	
Fork shroud – L	2	
Fork shroud – R	3	
Front brake, conical hub		Various spring, trunnions etc.
Front fork slider – R	1	For 1971/72 conical hub, NOS
Front fork, bottom yoke	2	New
Front fork, complete	1	For 1971/72 conical hub
Front fork, slider – L	1	
Front fork, top yoke	2	One possibly late T140 rather than T160
Hanger, silencer	9	5 x 71/72, 4 x 73/74
Head steady – L	2	
Head steady – R	4	
Headlight complete, flat back	1	1971/72 NOS

Sheet1

Horns, Clearhooter, high & low note	1 pr	NOS
Ignition coil	9	6 x 17M12, 3 x 17M6
Instrument carrier, T160, left	3	
Instrument carrier, T160, right	2	
Light panel, T160	1	
Mudguard, front	1	Wire stay type, late – good chrome but 40mm long dent at bottom
Mudguard, front, T160 with top bracket	1	Good chrome
Mudguard, rear, bracket, front bottom	6	
Mudguard, rear, bridge	6	
Mudguard, rear, clip & backing plate	2	
Oil cooler	1	NOS
Oil pipe retaining strap	3	
Oil tank	3	One with a small crack
P bolts, handlebar	6	
Pedal, rear brake	3	
Rear light, casting	3	
Reflector, red	2	For 1971/72
Seat hinge, front	3	
Seat hinge, rear	2	
Speedometer head, NVT	1	Not working – probably repairable
Speedometer head, NVT	1	Working (with a drill)
Speedometer head, orange needle	2	Not working – probably repairable
Speedometer head, orange needle	1	Working (with a drill).
Stand, centre	2	New
Stand, centre	5	
Stand, side	1	
Stop plate, centre stand	2	
Suspension units, rear	3 prs	Low mileage, good chrome on springs
Swinging arm with spindle etc.	3	One chromed
Swinging arm, T160.	1	NOS
Switch box, T160	2	
Tachometer gearbox, T160	1	
Tachometer head, NVT	1	Not working – probably repairable
Tachometer head, NVT	2	Working (with a drill)
Tachometer head, orange needle	2	Working (with a drill). One has no glass and a dirty face.
Tachometer head, orange needle (120mph)	1	Working (with a drill)
Tank badges, T160	1 pr	
Tool box	5	
Trim strip, export fuel tank	2	NOS. For 1970/72 tanks

Page 2

Sheet1

		0110011
Wheel rim, WM2 x 19"	2	1 x good chrome, 1 x not quite
Wheel, 16", rear, conical	1	With bearings.
Wheel, 18", rear, conical	1	With bearings.
Wheel, 19", front, disc	1	With bearings spindle.
Wheel, 19", rear, conical	1	With brake plate etc.
NONE TRIDENT ITEMS:		
Rear mudguard, stainless steel, universal	1	

Real muuguaru, staimess steet, universai		
Filler cap, flush, Harris	1	
Carburettors, Mikuni	3	1992 Trophy 900